



DR. SPANG

INGENIEURGESELLSCHAFT FÜR BAUWESEN, GEOLOGIE UND UMWELTTECHNIK MBH

DEVELOPER

Arnsberg District Authority, section 63 – old mines,
Dortmund

PROJECT

Cracks and damage on a residential building in Minden

- Cracks and damage on a 1.5-storey residential building on a hillside in Minden
- The cracks might be caused by near-surface coal mining

OUR SERVICES

- Inspection of mine plans and elevations
- Preparation of an investigation concept
- Preparation of tender documents
- Expert support for the investigative and stabilization measures
- Final documentation

