



DR. SPANG

INGENIEURGESELLSCHAFT FÜR BAUWESEN, GEOLOGIE UND UMWELTTECHNIK MBH

DEVELOPER

Großschirma Municipal Authority

PROJECT

Survey of flood damage, 06/2013

- Survey of damage to Großvoigtsberg fire pond
- Length of area to be inspected / river kilometres
- Survey of damage to Freiberg basin for properties for which the local authority is responsible
- 4 locations in total

OUR SERVICES

- Recording of all damage in or to the watercourse
- Recording of all damage to waterways management installations and bank fixtures
- Cost estimate for each damage location

